

# WELDVR

## Quick Start Guide User Manual



# Preparation



To get started open up the WeldVR hardcase and take out the Oculus Quest 2 Headset, Controllers, Controller Mount and Google Chromecast.



# Cast Computer


To start casting:

On your computer, open Google Chrome or Microsoft Edge and log in to your Meta Account.

Go to **oculus.com/casting**


Put your headset on and press on your controller to open the universal menu.

Select **Camera**, select **Cast** then select **Computer**.



Full Screen:


To get a full screen image click on the **settings icon** on the bottom right corner and toggle the **Widescreen (crop)** option.




# Launching WeldVR

Locate the WeldVR App in the installed Applications Menu on your Oculus Quest 2 Headset and launch it by clicking on it.


1



2




# WELDVR



# Enterprise Version Log In

To run the App in Enterprise Mode login with your admin credentials.




# Trainee Profile

## Log In with trainee profile

After logging in you will be prompted to select a trainee profile from the profile list located on the left side and enter a 4 digit pin to log in with the selected trainee profile.



New profiles can be added by clicking the Add New Profile button located on the bottom left side.



### Create a new user

Select user type

Trainee

Enter first name

Enter first name

Enter last name

Enter last name

Enter email

Enter email

Enter username

Enter username

Enter 4 digit pin

Enter 4 digit pin

CREATE USER

# Web-based Admin Panel

**WELD<sup>VR</sup>**

[console.cythero.com](https://console.cythero.com)

Users can also be added from the Admin Panel by clicking the plus button located on the upper right corner of the user list in the Organization Screen.