

WELDVR

Quick Start Guide User Manual



Content

1

Preparation

2

Launching WeldVR

3

Enterprise Version

Log In

4

Trainee Profile

Log in with trainee profile

5

Web-based Admin Panel

6

Switch to Single User

7

Download WeldVR App

Preparation




To get started open up the WeldVR hardcase and take out the Oculus Quest 2 Headset, Controllers, Controller Mount and Google Chromecast.


Plug in the Google Chromecast device to the TV, power on the Oculus Quest 2 Headset, go to the Apps, then press the Camera, click the Casting Icon and the Google Chromecast should appear. Select the device and start casting.




1



2



3



Cast Computer


To start casting:

On your computer, open Google Chrome or Microsoft Edge and log in to your Meta Account.

Go to **oculus.com/casting**


Put your headset on and press on your controller to open the universal menu.

Select **Camera**, select **Cast** then select **Computer**.



Full Screen:


To get a full screen image click on the **settings icon** on the bottom right corner and toggle the **Widescreen (crop)** option.



Launching WeldVR

Locate the WeldVR App in the installed Applications Menu on your Oculus Quest 2 Headset and launch it by clicking on it.


1



2




WELDVR



Enterprise Version Log In

To run the App in Enterprise Mode login with your admin credentials.




Trainee Profile

Log In with trainee profile

After logging in you will be prompted to select a trainee profile from the profile list located on the left side and enter a 4 digit pin to log in with the selected trainee profile.



New profiles can be added by clicking the Add New Profile button located on the bottom left side.



Create a new user

Select user type

Trainee

Enter first name

Enter first name

Enter last name

Enter last name

Enter email

Enter email

Enter username

Enter username

Enter 4 digit pin

Enter 4 digit pin

CREATE USER

Web-based Admin Panel

WELD^{VR}

console.cythero.com


Users can also be added from the Admin Panel by clicking the plus button located on the upper right corner of the user list in the Organization Screen.

Download WeldVR App Oculus Store

Login to your Meta Quest App and connect your Oculus VR headset with your Meta Account.



On Oculus Headset Dashboard click on the Oculus Store Icon



Search for WeldVR on the search bar, and select WeldVR App.



Click and then Download.

